

HABS
ORE
26-PORT,
8-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Venable Hotel (Hamilton Hotel)
1024 SW Third
Portland
Multnomah County
Oregon

HABS No. OR-159

John Stamets, Photographer March 6 and 7, 1993 (All Photos)

- OR-159-1 Context view looking to SSE along SW Third Avenue between Taylor and Salmon Streets. 180 mm.
- OR-159-2 Persepective view looking to SE at SW Third and Salmon Street. 90 mm.
- OR-159-3 Detail of main entry, lower marquee and the storefront immediately to the south of main hotel entry. 90mm.
- OR-159-4 West facade of the building. 65mm.
- OR-159-5 East facade of the building. 65mm.
- OR-159-6 South side of the building. 65 mm.
- OR-159-7 SW corner of building at SW Third Avenue and Main Street. 120mm.
- OR-159-8 Perspective view showing south and east sides of building as viewed from SW Second Avenue and Main Street. 120mm.
- OR-159-9 Detail of fire escape on north part of west facade of building. 180mm.
- OR-159-10 Lobby foyer and stairs viewed from front door. Partial tile pattern in foreground is seen in greater detail in photo No. OR-159-16. 90mm.
- OR-159-11 Typical hotel room (Room No. 206) on west side of second floor. 90mm.
- OR-159-12 Corridor on east side of 3rd floor showing doors to all guest rooms. View is looking north. 90mm.
- OR-159-13 Lobby. View looking east. 90mm.
- OR-159-14 View from lobby looking south into vestibule. 90mm.
- OR-159-15 Detail of lobby ceiling trum and molding in NW cornber of lobby. 210mm.
- OR-159-16 Detail of tiled "C" on floor at main entryway. Top of tile pattern is also seen in photo No. OR-159-10. 90mm.
- OR-159-17 Central stairwell viewed from 3rd floor landing and looking to SE. 65mm.
- OR-159-18 Detail of call box behind main lobby desk. 210mm.
- OR-159-19 Context view looking to NE from and through Chapman Square. 180mm.
- OR-159-20 Detailing of quoining on south corner of west side of building. 180mm.